Datamate Tooling

- Instruction sheets can be accessed at www.harwin.com/instructions.
- A Datamate Crimping Instruction video is available at www.harwin.com/harwintv.

REMOVAL TOOL For inserting crimped contacts into the rear > To aid removal of special cable contacts from Mix-Tek connectors. of mouldings. Instruction sheet available. Suitable for all Datamate signal Barrel crimp contacts. **ORDER CODE ORDER CODE** Barrel Signal crimps for Mix-Tek special Z80-280 Z80-290 L-Tek, J-Tek & Mix-Tek cable connectors **SCREWDRIVER** Recommended for unplugging L-Tek latched connectors Recommended for use on J-Tek board mount nuts. (tool releases the latches prior to disengagement). Board mount nuts and bolts to be tightened to a torque Can also be used with unlatched and friction latched of 21 ±2cmN. connectors. Suitable for all sizes. **ORDER CODE ORDER CODE** L-Tek **Z80-299** Z80-298 J-Tek screwdriver